
1/7



217

STRONG INFRA-RED RADIATION FROM ABOVE

TOP WELLS GET ALL THE HEAT AND DRY QUICKLY BEFORE BOTTOM WELLS DRY POSSIBLY OVERHEATING SAMPLES IN TOP WELLS WHEN THEY DRY OUT








Fig. 2a













SUBSTITUTE SHEET (RULE 26)



6/7



Power to Electronics

Power Supply

9

